



OIL AND GAS SITE REMEDIATION

CARTER COUNTY, OKLAHOMA
JANUARY 2023

Rose Rock provided remediation services for an oil and gas production company's site in Lone Grove, Oklahoma. Rose Rock assessed the release and took soil samples, which were then sent to a state-certified laboratory to be analyzed. Once results were received, the decision was made to remediate the release in place. The impacted area was tilled and treated with a heated power washer and a concentrate of two of Rose Rock's remediation products, EcoGreen and Salt Remediator. Once the area was fully remediated, a report was given to the client detailing the process and included pictures, lab analytics, as well as the Safety Data Sheets for both EcoGreen and Salt Remediator.



Consulting • Field Services • **Products**

Eco Degreaser • EcoGreen • Eco Rock Cleaner • Paraffin Solvent • **Salt Remediator** • Spill Kits

ROSE ROCK
PRODUCTS

P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockProducts.com