

DEGASSING AND CLEANING OF A CONTACTOR TOWER

GULF OF MEXICO
APRIL 2021

A turbo machinery specialist used EcoGreen to clean and degass the contactor tower of an offshore rig in the Gulf of Mexico. The goal of the cleaning was to increase the efficiency of sweet gas generation and to reduce corrosion and damage done to piping systems and process plants. A qualified, trained team divided the cleaning into four days in order to properly disassemble, power wash with EcoGreen, and reinstalled safely. EcoGreen successfully removed dirt generated by hydrogen sulfides, carbon dioxide, and aqueous amine solutions from the tower. Once complete, the efficiency of the equipment was restored, which in turn allowed the company to deliver quality gas and decreased corrosion in other equipment.







Consulting • Field Services • **Products**

Eco Degreaser • EcoGreen • Eco Rock Cleaner • Paraffin Solvent • Salt Remediator • Spill Kits



P.O. Box 721926 • Oklahoma City, OK 73172 • (405) 883-1095 • RoseRockProducts.com